	4	3	2	1	
В					В

## NOTES:

- 1. RELEASE TEMPERATURE: 35°F.
- 2. CARTRIDGE AND INSIDE OF HEX BODY MUST BE DRY BEFORE ASSEMBLY.
- 3. WARM THE CARTRIDGE TO AT LEAST 20°F ABOVE RELEASE TEMPERATURE BEFORE REINSTALLING.

ThermOmegaTech, Inc. 353 Ivyland Road Warminster, PA 18974-2205, USA	are provided for reference and evaluation and is subject to change without notice. The makes no representations, warranties or gua appropriateness, accuracy, completeness for any purpose, of the file, information or subject to the subject to t	This file and any associated information and specifications are provided for reference and evaluation purposes only, and is subject to change without notice. ThermOmegaTech makes no representations, warranties or guarantees as to the appropriateness, accuracy, completeness, or suitability for any purpose, of the file, information or specifications. You are solely responsible for the use of the file, information or specifications.		the property of contains confidential, rmation that is operty. Do not disclose or others except hermOmegaTech.	470-010100-035 MAGNUM CARTRIDGE	UNIT INCH [MM] SHEET
Ph: 215-798-5978	Tou are solely responsible for the use			NTS		1 of 1
4	3		2		1	

Α

COMPONENT LOCOMOTIVE FREEZE PROTECTION